

(108) HHDQ TYPE HOLDOWN - EXTERIOR WALL

121-08.2 NOT TO SCALE

SPECIAL STRUCTURAL

FOR BOLT PLACEMENT.

24" DIA.

(107) LIGHTPOLE BASE

101-01 NOT TO SCALE

INSPECTION IS REQUIRED

185-02M NOT TO SCALE

SIMPSON HOLDOWN AS INDICATED ON PLAN WITH ANCHOR PER

10. ANCHOR PER HOLDOWN SCHEDULE.

ANCHOR FOR SIMPSON HOLDOWN

121-08.1 NOT TO SCALE


NOT TO BE CONSIDERED AS

ANCHOR BOLT FOR SILL PLATE.

PER NOTE 10.

11. ANCHOR BOLT.

SIMPSON "HD" HOLDOWN - CORNER CONDITION



MICHAEL J.

WILDA 6.09/10/24//

NEW COMMERCIAL PAD
PAD 5B AT PASEO LINDO SHOPPING CENTER
NEC OF ARIZONA AVE AND OCOTILLO RD.
CHANDLER, AZ
STRUCTION SET

#24-121 ENG:GS 602-443-0303 Fax 602-443-0404 730 N. 52nd Street, Suite 105

Phoenix, Arizona 85008 mwilda@simplystructural.com

design by: GS drawn by: LV checked by: GS **S4.1**

project #: 23057

AT SIDEWALK EDGE

(106) TYPICAL CONCRETE TURNDOWN